

**PARTIAL INVENTORY OF TREES TO BE CLEARED  
BUTZ ROAD IMPROVEMENTS  
JULY 19, 2016**

Inventory includes all live trees and standing dead trees 12" diameter and larger standing within 10 feet of the road shoulder.

Inventory begins at junction with North Hollow Road and progresses toward Maston Hill Road.

Data is presented as being on left side of road or right side of road. Each of the trees tallied are tied in field notes to survey stations found in construction plans titled "Butz Road – T.H. 17 – Subbase, Drainage & Safety Improvements." So, each of the trees tallied could be found and examined by anyone interested in following my field notes.

ASP=aspen; WA=white ash; SM=sugar maple; RM=red maple; YB=yellow birch; BC=black cherry; BF=balsam fir; RS=red spruce; WP=white pine; PB=paper birch;

Norm Arseneault, Granville Tree Warden

**LEFT SIDE OF ROAD**

<u>Healthy Trees</u>											<u>Diseased/Dying Trees</u>								<u>Dead Trees</u>					<b>Standing</b>
ASP	WA	SM	RM	RS	YB	PB	ELM	BC	<u>TOTAL</u>		ASP	WA	SM	RM	YB	BF	BC	<u>TOTAL</u>		SM	BF	RM	WP	<u>TOTAL</u>
1	3	9	8	6	3	1	1	1	<b>33</b>		10	2	8	12	1	1	1	<b>35</b>		1	2	1	1	<b>5</b>

**RIGHT SIDE OF ROAD**

<u>Healthy Trees</u>										<u>Diseased/Dying Trees)</u>							<u>Dead Trees</u>				<b>Standing</b>
ASP	WA	SM	RM	RS	PB	BC	WP	<u>TOTAL</u>		ASP	WA	SM	RM	PB	BF	<u>TOTAL</u>		SM	BF	ASP	<u>TOTAL</u>
2	2	4	2	3	1	2	1	<b>17</b>		1	1	3	2	2	4	<b>13</b>		3	4	1	<b>8</b>

**Total Healthy Trees 50 45%**

**Total Diseased, Dying and Standing Dead Trees 61 55%**